

State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:				
OGM	Priscilla Burton Environmental Scientist III			
Company	Russell Hardy			

Inspection Report

Permit Number:	C0150007		
Inspection Type:	PARTIAL		
Inspection Date:	Thursday, June 30, 2005		
Start Date/Time:	6/30/2005 2:00:00 PM		
End Date/Time:	6/30/2005 5:00:00 PM		
Last Inspection:	Tuesday, May 31, 2005		

Inspector: Priscilla Burton, Environmental Scientist III

Weather: sunshine 80's

InspectionID Report Number: 658

Accepted by: whedberg 7/8/2005

Permitee: CONSOLIDATION COAL CO

Operator: CONSOLIDATION COAL CO MID-CONTINENT REGION

Site: **HIDDEN VALLEY MINE**

Address: PO BOX 566, SESSER IL 62884

County: **EMERY**

Permit Type: PERMANENT COAL PROGRAM

Permit Status: **RECLAIMED**

Current Acreages

Total Permitted	960.00
Total Disturbed	6.70
Phase I	6.70
Phase II	
Phase III	

	-	
Federal		✓ Underground
State		Surface
☐ County		Loadout
✓ Fee		Processing
Other		Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspection of road drainage and undisturbed diversion ditch. A plan of action to be implemented before the next inspection was discussed and agreed upon.

Inspector's	Signature
-------------	-----------

Date

Wednesday, July 06, 2005

Priscilla Burton, Environmental Scientist III

Inspector ID Number: 37

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150007 Inspection Type: PARTIAL

Inspection Date: Thursday, June 30, 2005

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable. b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	~		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures	~		✓	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.	o Roads: Drainage Controls	✓		✓	
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150007 Inspection Type: PARTIAL

Inspection Date: Thursday, June 30, 2005 Page 3 of 3

4.a Hydrologic Balance: Diversions

Rock fall from the cliff above the undisturbed diversion ditch will be removed prior to the next inspection, and the ditch will be two feet deep with 2h:1v side slopes as described in the August 12, 1997 revision of "The Amendment to Reclamation Plan Hidden Valley Mine Site Emery County, Utah" (sec. B, pg 3). Rocks cleared from the ditch will be left randomly on the A seam slope.

4.c Hydrologic Balance: Other Sediment Control Measures

At the base of the A seam, a double row of silt fence has accumulated more than 1 ft of sediment and, water has cut a new channel between the two rows of silt fencing. The Permittee will clean out the silt in front of the silt fences and replace old silt fencing with new silt fencing at the new surface elevations. Sediment will be cast aside on the A seam side to create an uneven ground surface. Where a new channel has been cut, the Permittee will create a dam in the channel using Fiberdam material or rock to slow the velocity of flow and encourage sedimentation. This work will be completed prior to the next inspection.

16.b Roads: Drainage Controls

Water bars along the access road (MRP, Plate III) divert flow to drainage channels that are treated with Landlok fabric and Fiberdam material. The Landlok fabric is no longer functioning as designed, as piping holes and undercutting is evident. Eight channels are shown to be treated with the Landlok fabric on Plate III. Each one was inspected and the action to be taken discussed with Mr. Hardy during the inspection. The Permittee will remove the Landlok fabric in all instances where it is no longer in contact with the ground surface, but retain the Fiberdam material. In some cases, the Permittee will replace the Landlok fabric with rock. This work will be completed before the next inspection.

Clearing the rocks and making other repairs (as noted below) will require a track hoe to pass over the access road only twice (entry and exit). A photo was taken of the road looking north from the stream crossing to establish current conditions. The site is very dry and lasting effects to the vegetation is not expected.

